

Message

From: Spurlin, Steve [Spurlin.Steve@epa.gov]
Sent: 4/12/2019 12:21:05 AM
To: Jardine, Rick [Jardine.Richard@epa.gov]; Garrard, Jordan [Garrard.Jordan@epa.gov]
Subject: draft ERNS update

Rick,

Use the same verbage related to our air sampling activities. You can indicate that arearae results have been below actionable levels and EPA plans to discontinue arearae sampling. EPA will continue work area monitoring and Colonial will continue work area monitoring and roving offsite monitoring, including residential areas North of the spill. No levels of concern have been detected off airport property. At approximately 1030hrs, fuel was discovered seeping into McCrory creek, but is currently contained by the existing booms. Colonial Pipeline initiated collection of the fuel and has installed additional booms at multiple downstream locations. An interceptor trench has been installed just upgradient of the seep and fuel is entering the trench. The pipeline has been repaired and is back in service. Rain is expected overnight and Colonial is attempting to cover the contaminated surface areas to prevent oil migration. Colonial conducted surface water sampling.

Probably other stuff I'm forgetting, but I had to do a lot of Jordans job today so tired....ha ha

Steve Spurlin
Federal On-Scene Coordinator
U S EPA, Region 4
Ed Jones Federal Bldg, B-13
109 S. Highland Ave
Jackson, TN 38301
Spurlin.Steve@epa.gov
731 394-8996